

НЕДОЛІКИ транспортно-пересадкового вузла “Святошин”

A photograph of a staircase leading up to a red door. The staircase has wooden steps and metal handrails. The walls are yellow, and the door frame is yellow. There is some debris on the stairs and the floor.

A photograph of a city street scene. In the foreground, a red-painted curb and a red trash can are visible. The ground is covered in snow and slush. In the background, there are several parked cars, a person walking, and a large, multi-story building with many windows. Bare trees line the street.



МАГІСТЕРСЬКА РОБОТА				Літера	Маса	Масштаб
Виконавця	Приймає	Підпис	Дата	MP		
Керівник Н. контр.	Гольман В.Є. Острін М. М. Богачук Д.О.					
Зав. кафедр.	Досвітні М.М.			Лист 8	Листів 11	
Неродопісний ТПВ				КНУБА кафедра МБ голова МБГ-61		